

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	211	(33/501.45).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	OFF	2006/01/06 10:19
L2	73	(33/501.08).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	OFF	2006/01/06 09:58
L3	80	(33/501.09).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	OFF	2006/01/06 10:01
L4	355	(33/501.05).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	OFF	2006/01/06 10:19
L5	94	(33/501.06).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	OFF	2006/01/06 10:10
L6	0	"fink.in"	US-PGPUB; USPAT; JPO	OR	ON	2006/01/06 10:20
L7	1920	fink.in.	US-PGPUB; USPAT; JPO	OR	ON	2006/01/06 10:20
L8	12	7 and ("33"/\$.ccls.)	US-PGPUB; USPAT; JPO	OR	ON	2006/01/06 10:21
L9	910	(73/865.9).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	OFF	2006/01/06 11:16
S1	129	(33/501.45).CCLS.	US-PGPUB; USPAT; JPO	OR	OFF	2006/01/06 09:53
S2	115	wear adj gauge	US-PGPUB; USPAT; JPO	OR	ON	2005/07/15 09:56
S3	13	S2 and ("33"/\$.ccls.)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/15 09:56
S4	39	(plasma adj processing adj tool)and(testing or measuring or gauge)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 14:42
S5	764	(73/865.9).CCLS.	US-PGPUB; USPAT; JPO	OR	OFF	2006/01/06 11:16

S6	148	S5 and (wear or deposit or defect)and(inspection or testing or measuring or comparing) (33/501.45).CCLS.	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 14:41
S7	129	(plasma adj chamber)and(gauge)	US-PGPUB; USPAT; JPO	OR	OFF	2005/07/20 16:00
S8	429	S8 and (wear or defect or deposit)	US-PGPUB; USPAT; JPO	OR	ON	2006/01/06 10:20
S9	282	(processing adj chamber) and ("33"/\$.ccls.)and(gauge)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 15:00
S10	0	(chamber) and ("33"/\$.ccls.)and(gauge)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 16:00
S11	300	S11 and (wear or deposit)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 16:03
S12	56	(plasma adj chamber) and ("33"/\$.ccls.)and(gauge)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 16:01
S13	1	(plasma adj chamber) and ("33"/\$.ccls.)and(gauge)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 16:04
S14	0	(plasma adj chamber) and (wear adj gauge)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 16:05
S15	1	(plasma adj chamber) and (deposit adj gauge)	US-PGPUB; USPAT; JPO	OR	ON	2005/07/20 16:05
S16	7999	plasma adj chamber	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2006/01/04 17:03
S17	2433	S16 and (gauge or gap)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2006/01/04 17:05
S18	509	S16 and (gauge)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2006/01/04 17:42
S19	0	S16 and ((wear or tear or deposit)adj(measurement))	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2006/01/04 17:43
S20	3252	S16 and (wear or tear or deposit)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2006/01/04 17:43

S21	612	S16 and (tolerance)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2006/01/04 17:44
S22	296	(33/502).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	OFF	2006/01/04 18:27
S23	211	((go)and(no adj go))adj gauge	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2006/01/04 18:41
S24	26	S23 and chamber	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2006/01/04 18:41